



OEPA  
SEDO

CLOW WATER SYSTEMS COMPANY

2007 JAN 22 AM 11:08

January 16, 2007

2266 South Sixth Street  
P.O. Box 6001  
Coshocton, Ohio 43812-6001  
(740) 622-6651  
FAX (740) 622-8551

Zach Hamlin  
Ohio EPA, SEDO  
Division of Air Pollution Control  
2195 Front Street  
Logan, Ohio 43138-9031

**Re: 4<sup>th</sup> Quarter Deviation Report and 2<sup>nd</sup> Half 2006 Semi-annual Report**  
**Clow Water Systems Company**  
**Coshocton, Ohio**  
**Facility ID: 06-16-01-0006**

Dear Mr. Hamlin,

Please find enclosed the 4<sup>th</sup> quarter deviation report and semi-annual report in accordance with the Title V Permit for Clow Water Systems Company located in Coshocton, Ohio.

If you have any questions or require additional information, please feel free to contact me at 740-291-1087.

Sincerely,

Heather A. Klesch  
Environmental Manager  
Clow Water Systems Company

**4th Quarter 2006 Deviation Report (October 1, 2006 - December 31, 2006) and  
Semi-annual Report (June 1, 2006 – December 31, 2006)**

<b>Unit</b>	<b>Parameters</b>	<b>Findings</b>
F002	Visible emissions	No deviations
F005	VOC limits	No deviations
	Visible emissions	No deviations
F022	No deviations	No deviations
	Visible emissions	No deviations
F014	VOC limits	No deviations
	Visible emissions	No deviations
	<b>Total VOC Emissions (annual)</b>	<b>0.26 tons</b>
K002	Non-compliant coatings	None used
	Filtration system	No deviations
K005	Non-compliant coatings	None used
K006	Non-compliant coatings	None used
	Filtration system	No deviations
K007	Non-compliant coatings	None used
K008	Non-compliant coatings	None used
K009	Non-compliant coatings	None used
	VOC limits	No deviations
	<b>Total VOC Emissions (annual)</b>	<b>2.17 tons</b>
P033	Non-compliant fuels	None used
P901	Exhaust gases burned at 1300°F min.	Please See Below
	Minimum 35" H <sub>2</sub> O DP across venturi	Please See Below

Emission Unit P901 – Cupola

Afterburner Temperature < 1300 F


Date	Duration (minutes)	Cause	Conclusion
11/10/06	23	Emission tube plugged	Meltout/shutdown/clean tube
11/15/06	8	Shut down/start up	Stabilized system

Pressure < 35 inches and > 60

Date	Duration (min)	Cause	Solution
10/30/06	30	Venturi stuck	Shut down/maintenance
11/22/06	30	High dp (61)	Opened venturi
12/04/06	30	Plugged lines	Electricians repaired

Certification

Based on information and belief formed after reasonable inquiry, the statements and information in this report are true, accurate and complete.

A handwritten signature in black ink, appearing to read "Jeff Otterstedt", is written over a horizontal line.

Jeff Otterstedt, Vice President/General Manager

1-18-07

Date